# Weathertzenton Assistance Program

# Work Order (Bid Form)

Richard Goddard 615-812-8955

# **WORK ORDER INFORMATION**

Work Order Name: WO/90009MD2658/1

Work Order Type: Weatherization

Audit Name: 90009MD2658

## **CLIENT INFORMATION**

Client Name: Address:

Client ID: 90009MD2658

Alt. Client ID: Davidson

### **AGENCY INFORMATION**

Agency: Metropolitan Development and Housing Agency Agency Phone: (615) 252-8500

Address: 701 South Sixth Street Fax: (615) 252-8533

Nashville, TN 37206 Email Address:

Company Name & License Number:	
Contractor's Signature:	

### **COMMENT**

Audit performed 3 Apr 12, Site built 1967, Brick, 1125 SQFT. Home has unconditioned storage are (12x25 - No measures to this area) There is a dog that has a history of biting.

Client Name:
Client ID: 90009MD2658
Alt. Client ID: Davidson

Work Order (Bid Form)
Work Order Name: WO/90009MD2658/1

DOE Weatherization Assistant Version 8.6.0

Report Run On: 4/4/2012

Page 1 of 7

Measure 1 Infil	tration Redctn			Componen	ts			Inspected
1. Seal 2. Win2 3. Win3 4. Win3 5. Door	on reduction measures: vent thru cabinet at kitch (qty=2) - Caulk, Glaze (qty=2) - Caulk, Glaze (qty=2) - Caulk, Glaze 1 - DS 2 - Provide solid door, W			loor from kit	chen to st	torage		
7. Rem	ove 4 window AC units (d	only if cent	tral unit		•		Actual	
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
<ul><li>Miscellaneous St</li></ul>	-	Each	1		, ota,	Q.y		rotar
Other Detail								
			Measure	e Sub Total:			Sub Total:	
	<b>H Tank Insulation</b> Tank insulation 40 gal, ta	ll, electric		Componen	ts			Inspected
				Estimated	<u> </u>	-	Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equip	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measure	e Sub Total:		:	Sub Total:	
Field Notes:								

Client Name:
Client ID: 90009MD2658
Alt. Client ID: Davidson

Measure 3 DW	'H Pipe Insulation			Componen	its			Inspected
Comment DWH -								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 4 Wa	Il Inculation			Componen	to \\/\ 1 \	\ <u>\</u> \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	// 3 /// /	Inspecte
		-41-5-4-	and a second second	•	•	-	,	
	1,2,3 - Brick exterior, Shee			sulation pro	cess exp	iained i	Ю	
	and she is ok with drilling			!	-l			
	between house and stor							
	ner's permission if insulation						_	
	on must be returned to an factory to client."	парреага	iiice as	Close to on	yırıaı as p	JUSSIDIE	<b>=</b>	
	,			Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation -	SqFt	960.3					
	Cellulose, Blown - 2x4 Filled							
2. Labar		0 54	000.0			]		
2 Labor	Wall Insulation - Cellulose, Blown - 2x4	SqFt	960.3					
	Filled							
Other Detail						7	1	
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Measure 5 Floo	or Ins. R-19			Componer	nts F1		1	Inspected
Comment Joist 2x	10 16"OC							
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1125					
2 Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1125					
Other Detail								
			Magazz	e Sub Total:		] ]	Sub Total:	
			Weasur	e Sub Total.				
work, th meet ar	e App 2 ton Package or sp nermostat. Disconnect all nd comply with Metro Mec ngly by a licensed HVAC	radiant h chanical (	neaters Code. M	at panel bo	ox. Systen n Manual	n must		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipme		Each	1		i otai			Total
2 Labor	Heatpump - 22 kBtu/h Existing, Consult Manual J Data	Each	1					
Other Detail								
			Measur	e Sub Total:		1	Sub Total:	
Field Notes:								
rieia ivotes:								

Client Name:
Client ID: 90009MD2658
Alt. Client ID: Davidson

Work Order (Bid Form)


DOE Weatherization Assistant Version 8.6.0

Work Order Name: WO/90009MD2658/1 Report Run On: 4/4/2012

				•	ts A1			
between	app 4 inches blown cello every rafter at top plate e (SWFG p.3-14).					fles		
				Estimated	1		Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	Attic Insulation - Cellulose, Blown - R-11	SqFt	1125					
Labor	Attic Insulation - Cellulose, Blown - R-11	SqFt	1125					
Other Detail								
			Measure	e Sub Total:		] ;	Sub Total:	
	Nonitor is Needed			Componen				Inspecte
Comment				Estimated	<u> </u>		Actual	
Comment  Material / Labor	Description / Comment	Units	Qty	•		Qty		Inspecte
Comment  Material / Labor	Description / Comment	<i>Units</i> Each		Estimated	<u> </u>	Qty	Actual	
Comment  Material / Labor  Health and Safety	Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual	
Comment  Material / Labor  Health and Safety  Labor	Description / Comment CO monitor	Each	<b>Qty</b> 1	Estimated	<u> </u>	Qty	Actual	
Comment  Material / Labor  Health and Safety  Labor	Description / Comment CO monitor	Each	<b>Qty</b> 1	Estimated	<u> </u>	Qty	Actual	
Comment  Material / Labor  Health and Safety  Labor	Description / Comment CO monitor	Each	<b>Qty</b> 1	Estimated	<u> </u>	Qty	Actual	
Comment  Material / Labor  Health and Safety  Labor	Description / Comment CO monitor	Each Each	<b>Qty</b> 1 1	Estimated	<u> </u>		Actual	
Measure 8 CO Notes:	Description / Comment CO monitor	Each Each	<b>Qty</b> 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
Material / Labor Health and Safety Labor Other Detail	Description / Comment CO monitor	Each Each	<b>Qty</b> 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

<i>Measur</i> e 9 Fix Fa	Not Operational Kitcher	n Exhaus	t	Componen	ts		1	Inspected
	n exhaust - replace non w of) (white)	orking 36'	" kitche	n exhaust (	already v	ented		
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safe	y Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail			1			7		
						] []		
			Measur	e Sub Total:			Sub Total:	
Measure 10 Ins	tall Bathroom Eyhaust F	an		Componen	nte .			Inspected
Comment Install	tall Bathroom Exhaust F Bath exhaust fan (none e e switch, Pull electricity fro	xists), ven			soffit &	cap,	Actual	Inspected
Comment Install provide	Bath exhaust fan (none e	xists), ven		erior wall or	soffit &	cap,		Inspected
Comment Install provide	Bath exhaust fan (none e e switch, Pull electricity fro	xists), ven om nearby	circuit	erior wall or <i>Estimat</i> ed	soffit & o		Actual	
Comment Install provide  # Material / Labor  1 Health and Safe	Bath exhaust fan (none exercite switch, Pull electricity from Description / Comment	xists), ven om nearby <i>Units</i>	circuit Qty	erior wall or <i>Estimat</i> ed	soffit & o		Actual	Inspected
Comment Install provide	Bath exhaust fan (none ei e switch, Pull electricity fro Description / Comment ty Bathroom exhaust fan	xists), ven om nearby <i>Units</i> Each	circuit  Qty  1	erior wall or <i>Estimat</i> ed	soffit & o		Actual	
Comment Install provide  # Material / Labor  1 Health and Safe  2 Labor	Bath exhaust fan (none ei e switch, Pull electricity fro Description / Comment ty Bathroom exhaust fan	xists), ven om nearby <i>Units</i> Each	circuit  Qty  1	erior wall or <i>Estimat</i> ed	soffit & o		Actual	
Comment Install provide  # Material / Labor  1 Health and Safe  2 Labor	Bath exhaust fan (none ei e switch, Pull electricity fro Description / Comment ty Bathroom exhaust fan	vists), venom nearby  Units  Each  Hour	circuit  Qty  1  1	Estimated Unit Cost	soffit & o	Qty	Actual Unit Cost	
Comment Install provide  # Material / Labor  1 Health and Safe  2 Labor	Bath exhaust fan (none ei e switch, Pull electricity fro Description / Comment ty Bathroom exhaust fan	vists), venom nearby  Units  Each  Hour	circuit  Qty  1  1	erior wall or <i>Estimat</i> ed	soffit & o	Qty	Actual	
Comment Install provide  # Material / Labor  1 Health and Safe  2 Labor	Bath exhaust fan (none ei e switch, Pull electricity fro Description / Comment ty Bathroom exhaust fan	vists), venom nearby  Units  Each  Hour	circuit  Qty  1  1	Estimated Unit Cost	soffit & o	Qty	Actual Unit Cost	

Measure 11 Smo	ke Detector is Needed	l		Componer	nts			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Smoke detector	Each	2					
2 Labor	Labor	Each	2					
Other Detail						<b>_</b>		
						] []		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
-	or Barrier Needed			Componer	nts			Inspected
•	ement/Crawlspace) apor barrier on ground	and 12" up	found	ation wall &	secure,	(overlar	)	
	2" and seal). Crawlspa							
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
0 Unspecified	Basement / crawlspace vapor barrier (+)	Each	1					
Other Detail								
		ı	Measur	e Sub Total:		]	Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	



EAST